

- 1 Tall entrance gates
- 1a Interactive signage
- 2) Widened gravel entrance track
- (2a) Planted island to block sight lines
- 2b Planting / greening of fences
- (2c) Greening of walls / living fruit walls / bird and bee
- (2d) Greening of roof as extension of wildflower meadow habitat
- (2e) Planting island to replace railing
- (2f) Increased greening and planting areas within tarmac payement
- 3 Existing access lane retained
- 3 Controlled access lane gate for resident vehicles
- (4) Staggered gate into reserve, pedestrian access only
- (5) Concealed maintenance storage
- 6 Concealed bird / wildlife hide
- Concealed store for local groups (e.g. Cub Scouts / Brownies)
- 8 Educational controlled enclosure for observing and learning about the reserve
- 9 Controlled viewpoint along river bank (not across) 🛦
- (10) Raised slopes to vary terrain and enclose reserve
- (11) Interpretation boards
- (12) Terracing along length of northern edge (left bank) to mitigate erosion of bank and create habitat
- 13 Tree retained where possible or replaced
- (14) Wild flower meadow
- (15) Natural seating area with fallen trees
- (16) Backwater inlet and refuge, and reeded tidal water habitat
- (17) Stepping stones
- 18 Timber decks around inlet
- (19) Fence removed and hedge introduced along length of lane
- 20 Perimeter thicket habitat and natural screening of large scale planting/ trees / brushes along full length of northern edge (left bank)
 N.B. Fence retained and absorbed/substituted
- within thicket over time
 ②1 Controlled / fence access to mooring (no other access to river)
- 22 Mooring posts
- (23) Gravel path (wheelchair accessible)
- 24 Life-ring
- (25) Orchard and controlled market garden