Bradenham Parish Council Risk assessment for the Lych gate in the church wall Bradenham Village

Assessor	D Hansen.		
----------	-----------	--	--

Date...25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Seating	Risk of injury from fixed seating	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3	3	9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.
4	Roof tiles falling off	Risk of injury due to roof tiles falling off the roof	4	1	4	Carry out annual inspections and repair and identified defects.

Risk Assessment Matrix

X	5	4	3	2	1
5	<mark>25</mark>	20	<mark>15</mark>	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the two dog bins in Bradenham Village and the one along the A4010 by the entrance to the bunker road

AssessorD Hansen	Date25/10/25
------------------	--------------

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or	4	1	4	Carry out annual inspections and repair any
		complete structure				identified defects
2	Slips, trips and falls	Risk of slips, trips and falls from debris		3	9	Ensure area is kept clean and maintained in
						good condition.
						Carry out annual inspections.

Risk Assessment Matrix

X	5	4	3	2	1
5	25	20	<mark>15</mark>	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the bus shelter on A4010 opposite the Red Lion

AssessorD Ha	nsen
--------------	------

Date.....25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Seating	Risk of injury from fixed seating	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris		3	9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.

Risk Assessment Matrix

X	5	4	3	2	1
5	25	20	<mark>15</mark>	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the bus shelter on A4010 on the Red Lion side of the Road

AssessorD Hansen	Assessor	D Hansen	
------------------	----------	----------	--

Date.....25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Seating	Risk of injury from fixed seating	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3	3	9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.
4	Roof tiles falling off	Risk of injury due to roof tiles falling off the roof	4	1	4	Carry out annual inspections and repair and identified defects.

Risk Assessment Matrix

Х	5	4	3	2	1
5	<mark>25</mark>	<mark>20</mark>	<mark>15</mark>	<mark>10</mark>	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the bus shelter on New Road, Walter's Ash

Assessor	D Hansen.	

Date.....25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Seating	Risk of injury from fixed seating	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3	3	9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.

Risk Assessment Matrix

X	5	4	3	2	1
5	<mark>25</mark>	20	15	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	<mark>10</mark>	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the Notice board in Bradenham Village

AssessorD	Hansen
-----------	--------

Date...25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Doors blowing open	Risk of injury from doors	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3 3 9		9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.

Risk Assessment Matrix

X	5	4	3	2	1
5	25	20	<mark>15</mark>	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the Notice board on Bradenham Woods Lane, Walter's Ash

Assessor	.D Hansen	
----------	-----------	--

Date.....25/10/25.....

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or complete structure	4	1	4	Carry out annual inspections and repair any identified defects
2	Doors blowing open	Risk of injury from doors	2	2	4	Carry out annual inspections and repair any identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3	3	9	Ensure area is kept clean and maintained in good condition. Carry out annual inspections.

Risk Assessment Matrix

X	5	4	3	2	1
5	<mark>25</mark>	20	<mark>15</mark>	10	5
4	<mark>20</mark>	16	12	8	4
3	<mark>15</mark>	12	9	6	3
2	<mark>10</mark>	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always

Bradenham Parish Council Risk assessment for the Red ex-BT phone box on Bradenham Woods Lane Bradenham

The phone box is used to house the village defibrillator not owned by the parish council

Assessor D Hansen	Date25/10/25

Persons affected: Public, employees, contractors

	Hazards identified	Risk	S	L	R	Control Measures
1	Structural collapse	Risk of injury due to collapse of part or	4	1	4	Carry out annual inspections and repair any
		complete structure				identified defects
2	Glass breaking	Risk of injury due to cut glass	2	2	4	Carry out annual inspections and repair any
						identified defects
3	Slips, trips and falls	Risk of slips, trips and falls from debris	3	3	9	Ensure area is kept clean and maintained in
						good condition.
						Carry out annual inspections.
4	Door slamming on user	Risk of injury door closing whilst trying to	4	2	8	Carry out monthly inspections and repair
		enter				and identified defects.

Risk Assessment Matrix

X	5	4	3	2	1
5	<mark>25</mark>	20	15	10	5
4	20	16	12	8	4
3	15	12	9	6	3
2	10	8	6	4	2
1	5	4	3	2	1

Severity		Likelihood
No injury	1	Almost never
Minor injury	2	Seldom
Injury	3	Possible
Serious injury	4	Probable
Death	5	Almost always